

## Subdivisional Lines of T 4 N R. 38 E., W.M.

Chains		Feet
	<p>marked T 4 N R 37 E S 25 B T</p> <p>A fir, 5 ins. diam. brs. N. 60° W., 46 lks. dist. marked T 4 N R 37 E S 24 B T.</p> <p>Thence I run</p> <p>E. on true line bet. Secs. 19 &amp; 30, with same Var.</p>	
39.77	<p>Set a basalt stone, 16 x 12 x 3 ins., 11 ins. in ground for <math>\frac{1}{4}</math> Sec. Cor., marked <math>\frac{1}{4}</math> on N. face, dug pits, 18 x 18 x 12 ins., E. &amp; W. of Cor. 5<math>\frac{1}{2}</math> ft. dist. and raised a mound of earth, 1<math>\frac{1}{2}</math> ft. high, 3 ft. base alongside of Cor.</p>	
79.77	<p>The Cor. to Secs. 19, 20, 29 &amp; 30</p> <p>Land; hilly</p> <p>Soil; gravelly, 3rd rate.</p> <p>Timber, dense pine, fir, 30 Chs.</p> <p>Scattering pine and fir, 49.77 Chs.</p> <p>Thick undergrowth; greasewood, fir and pine, 79.77 Chs.</p> <p style="text-align: right;">Sept. 23, 1883</p>	
<hr/> <p>Note:- The remaining portion of this township is broken by a succession of deep rocky canyons which renders its subdivision impracticable.</p> <hr/>		
<p>General Description</p> <hr/>		
<p>The S. part of this tp. is high, rolling and generally covered with a dense forests of pine, fir and tamarack timber. The soil is of good 2nd rate, quality.</p> <p>There is one settler in Sec. 33.</p> <p>The northern part of the tp. is so rough as to render its subdivision impracticable.</p> <hr/>		
<p>Subdivisional Lines of T 4 N R 38 E., W.M. (Retracement) As surveyed by Robert F. Omeg, U.S. Deputy Surveyor Under Contract No. 761, Dated June 16, 1905</p> <hr/>		
<p>Preliminary to commencing the subdivsion of this tp. I retrace the old lines of survey, as follows:</p> <p>I commence at the Cor. to Secs. 13, 18, 19 &amp; 24, on the E. Bdy. of the Tp., thence I run,</p>		