

Found 1/2" Iron Rod Located By Frank Hayes County Surveyor

Replaced With Iron Spike Imbedded in Concrete 2' below Existing Ground surface 1/2" Iron Pin Flush With Existing Ground at 1/16

Found Original Rock Corner Identified By County Surveyor

5  
8

4  
9

2619.45

1309.725

1309.725

1866.90

4  
3

9  
10

1/2" Iron Pin 3' Below Existing Ground

1" Iron Pin 3' Below Existing Ground

1/2" Iron Pin 2' Below Existing Ground

1/2" Iron Pin 2' Below Existing Ground

5255.70

1322.78

1322.78

1/2" Iron Pin 2' Below Existing Ground

1336.13

1336.13

Found Original 1/4 Corner Stone Found Iron Spike for 1/16 corner

Replaced with Iron Spike Imbedded in Concrete 2' below Existing Ground

8  
17

9  
16

2693.91

9  
16

10  
15

Note:

Traverse Intersects South Line of Section 9 10.00' West at Section Corner

THE CITY OF PENDLETON			
OFFICE OF THE CITY ENGINEER			
<b>SECTION 9</b>			
<b>T 2 N R 32 E W M</b>			
DR BY: <i>Charles Callahan</i>	IMPROVEMENT DIST. NO.		
CK. BY:			
SCALE: 1" = 500'	DATE: 3-23-54	DRG. NO.: B-54-21-M	

06-437-B