

G-414-B

Q-414B

219

2N32 15 A

REGISTERED OREGON LAND SURVEYOR  
ENGINEERING DEPARTMENT  
CITY OF PORTLAND

Filed 7/27/61

WHL

7-24-61

I, CHARLES A. EDDLEMAN, DO  
DEPOSE AND SAY THAT THE  
SUBDIVISION OF SECTION 15 WAS DONE  
UNDER MY DIRECT SUPERVISION  
AND THE WORK WAS PROPERLY  
PERFORMED AND EXECUTED.

Charles Allen Eddleman  
7-24-61

REGISTERED  
OREGON  
LAND SURVEYOR  
Charles Allen Eddleman  
OCT. 15, 1933  
CHARLES ALLEN EDDLEMAN  
388

REGISTERED  
OREGON  
LAND SURVEYOR

OCT. 15, 1933  
CHARLES ALLEN EDDLEMAN  
388



REGISTERED OREGON LAND SURVEYOR  
ENGINEERING DEPARTMENT  
CITY OF PORTLAND

COMPLETED FROM SURVEYS  
BY TOWN OF  
EDDLEMAN  
1953 ±

CITY OF PORTLAND  
ENGINEERING DEPT.  
RECORDS AREA  
SECTION 15  
319

Flood  
Wax

7/27/41

JAN 1956

Eddleman T

Renzog AC

Hays

Sub Division Section

TAN P 32 EMM

The first step  
Find the original  
and I found the  
North West corner  
replaced by the  
on file at the county  
between sections 15 &  
Rock Monument a large  
wide of the existing  
said rock marked with  
South West corner  
unable to find  
County Surveyor Frank  
the corner post, at  
sections 15 and 22. A mound  
at the South East corner  
intersection of monument  
line to the south, at  
15 and 14 I could

in this survey was to  
government corners  
following points: In the  
I found a  $\frac{1}{2}$ " iron rod as  
city survey at 1954 and  
Court House, At the corner  
16 I found the original  
painted Basalt Rock if not  
ground level. The top of  
a deep cross. At the  
at section 15 I was  
the monument so the  
Hayes said he would accept  
the  $\frac{1}{4}$  corner between  
at rocks covered with dirt,  
of section 15. No fence  
of any type, could see a fence  
line  $\frac{1}{4}$  between sections  
find No type of monument

At the North East  
only a Fence post  
the county Surveyor  
Sections 10 and 15  
govern ment Corner, there  
the west a bout 15'  
with J.C. Arnold Survey  
between the the two  
I reset the S corner with  
at South West Corner  
East 26000 feet  
with 4" of dirt. At 529,  
the point dis agree  
the south, I placed a  
South East Corner  
at 2640 feet at the  
15 & 22. Starting  
section 15 we chained  
East Corner of section  
5<sup>3</sup> 46.20 feet. I  
at 2673.10 feet for the

At the North East  
only a Fence past  
the county Surveyor  
Sections 10 and 15  
government corner, there  
the west a part 15'  
with J.C. Arnold Survey  
between the the two  
I reset the  $\frac{1}{4}$  corner with  
at South West Corner  
East 2640.00 feet FOUND  
with 4" of DIAM. AT 5280  
THE POINT DID AGREE  
THE SOUTH. I PLACED A  
SOUTH EAST CORNER  
AT 2640 FEET AT THE  
15 & 22. STARTING AT  
SECTION 15 WE CHAINED  
SOUTH CORNER OF SECTION  
2640.20 FEET. I  
AT 2673.10 FEET FOR THE

Corner of section 15 I found  
which was accepted by  
at  $\frac{1}{4}$  corner between  
I did not find the  
was a fence corner to  
but it did not agree  
or the measured distance  
accepted section corners  
a 1" iron pin. Starting  
at section 15 WE CHAINED  
MOUND OF ROCKS COVERED  
FEET FOUND NO MONUMENT  
WITH THE FENCE LINE FROM  
Hub UNDER THE FENCE AT  
OF SECTION 15 AND A Hub  
 $\frac{1}{4}$  CORNER BETWEEN SECTIONS  
THE NORTH EAST CORNER OF  
SOUTH TO THE SOUTH  
15, THE DISTANCE WAS  
PLACED A 1" IRON PIPE  
 $\frac{1}{4}$  CORNER BETWEEN SECTIONS 15 & 14

REGISTERED  
OREGON  
LAND SURVEYOR

*Charles Allen Eddleman*

OCT. 15, 1956  
CHARLES ALLEN EDDLEMAN  
333