

OREGON CORNER RESTORATION FORM

Section 25 Township 1 N Range 33 EW

County Umatilla Date 12 October 2004 R-21

CORNER DESIGNATION

Northwest Corner Section 25

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

David Chapman, Contract 107, September 21, 1864


Zenas F. Moody, Contract 164, October 4, 1871

Monument(s) & Accessories Found: (Condition and Source)

Road North-South, Fence Line East. Also found nail from C.S. No. 90-20B.

Monument Detail

Sketch



2 1/2" BRASS CAP  
ON 1 1/2" X 30"  
IRON PIPE

Monument Set (Procedures and Description)

Set Brass Cap, Stamped PLS 933 on Cap

Set 5/8" X 30" Iron Rebar 25 feet East and West. Set

Set 5/8" X 30" Iron Rebar 30 foot N 45° E and S 45°W, w/ Alum.

Cap stamped PLS 933

New Accessories

Location Poster on Fence Corner

Location & Comments

1 1/2 mile South of  
Spring Cr. Rd.

Compass Declination \_\_\_\_\_

Firm/Agency \_\_\_\_\_

Krumbein Engineering LTD.

Address 361 SE 2nd


Pendleton, OR. 97801

Party Chief Dave Krumbein

Notes \_\_\_\_\_

Witness \_\_\_\_\_

Surveyor's Seal



RENEW 6/30/05

04-182-B