Exterior Bdy. of T. 4 N., R. 38 E., W.M. (N. Bdy.)

Chains		Feet
	measured a base to S. 150 lks. which formed an angle of 8½° whence	
	Sine 8½° : Co Sine 8½° : : lks. : lks. 1481 : .9889 : : 1.50 : 10.01	
	A small brook, about mid way	
65.76	To flag	
80.00	A pine, 32 ins. diam. on S.E. face of bluff for Cor. to Tps. No. 5 N., Rgs. No. 38 & 39 E. W.M., on first Standard Parallel N., from which	
	A pine, 4 ins. diam. brs. N. 41° E., 37 lks. dist.	
	A Pine, 13 ins. diam. brs. N. 20° W., 13 lks. dist.	
	Land; surface very mountainous and broken	
	Soil; 3rd rate and worthless	
	Some good timber, fir and pine, but mostly scattering	
	This whole line of six miles runs along the S. side of the dividing ridge bet. the N. and S. forks of the Walla Walla River and is very broken, being a continued succession of spurs and gulches and has a general southern slope.	
	June 4th, 1879.	

Resurvey of Exteriors of T 5 N R 38 E., W.M.
As surveyed by Geo. R. & Wm. E. Campbell, U.S. Deputy Surveyors
Under their Joint Contract No. 699, Dated Feb. 9, 1899.

I just determine by retracement, that the E. bdy. while very nearly correct in alignment is defective in measurement and that the Cors. thereon in some instances are partically or wholly obliterated.

I run W. on a blank line on S. Bdy. of Sec. 36 and at 13.30 chs. intersect the Closing Cor. of T 4 N., Rgs. 38 & 39 E., at 44.75 chs. intersect the standard ¼ Sec. Cor and at 85.10 chs. intersect the standard Cor. of Secs. 35 & 36; therefor I continue my lines W. and at 165.10 Chs. intersect the standard Cor. for Cors. 34 & 35, having found old tree of the standard ¼ Sec. Cor. 203.10 Chs. intersect the standard ¼ Sec. Cor. S. Bdy. of 34; at 241.10 Chs. intersect the standard Cor. of 33 & 34; at 280.79 Chs. fall 22 lks. S. of the standard ¼ Sec. Cor., S Bdy.