

**OREGON CORNER RESTORATION FORM**

Section 9 Township 1N Range 32E  
County Umatilla Date: August 17, 2009

Corner Designation: 1N32J13

Condition Report Only  
 Not found  
 Remonumented  
 Unrecorded  
 Surveyed in  
 Referenced out


Corner common to sections 9, 10, 15, and 16, T1N, R32E, W.M., Umatilla County, Oregon.

Previous Renewals / Surveys, etc.  
Corner was originally set by Daniel Chaplin under contract No. 107, dated September 21, 1864. His record reads: Set post for corner to secs. 9, 10, 15 and 16 in mound of earth with charred stake ,pits &c as per instructions. David H. Krumbein under survey 85-33-B stated: found fence corner. William R. Wells under survey 96-167-B states: set brass cap.

Monument and Accessories found: ( condition and source )  
I found the brass cap by Wells marked as shown below in good condition.

**DIAGRAM**

**SKETCH**



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)  
None. The purpose of this certificate is to report the State Plane Coordinates of the corner.

For references:

The monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments  
NAD 83/1991 State Plane Coordinate  
Oregon North Zone  
N = 699,653.55 ift  
E = 8,635,445.08 ift

Compass Declination

Surveyors Seal

RECEIVED BY:  
Umatilla County Surveyor  
Date: 6-10  
Rec'd By: KK  
No. 10-93-C

Firm / Agency  
Witness Tree Surveying  
Address  
P.O. Box G  
Pilot Rock, Or. 97868  
Party Chief  
Stephen K, Haddock

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Stephen K. Haddock*

OREGON  
JULY 9, 2001  
STEPHEN K. HADDOCK  
56295LS

RENEWAL DATE 6-30-11