

OREGON CORNER RESTORATION FORM

Section 4 Township 3N Range 33E

E-11

County Umatilla Date 11-8-85

CORNER DESIGNATION

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. None

Monument(s) & Accessories Found: (Condition and Source)

None

Monument Detail

Sketch



plow line

plow line

● BC

Monument Set (Procedures and Description)

2 1/2" Brass Cap on 1 1/2" galvanized pipe set 20 feet East of a North-South running plow line and 20 feet North of a faint West running plow line and buried 12" below surface

New Accessories

None

Location & Comments

Surveyor's Seal

Compass Declination _____

Firm/Agency Krumbein

Engineering Ltd

Address 361 S.E. Second

Pendleton, Oregon 97801

Party Chief R. Panches

Notes _____

Witness S. Carlson

RECEIVED BY

Umatilla County Surveyor

Date 6-26-86

Rec'd By KA

No. 86-72-R

