


CERTIFICATE OF RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey was made by Wm. H. Odell, US Deputy Surveyor under contract No. 114 dated July 2, 1866. The section corner was set on Oct. 12, 1866.

A resurvey was made by George S. Pershin under Contract No. 332 dated July 29, 1879. The corner was again set on Aug. 25, 1879. He set the following bearing trees:  
 A tamarack 4" dia. bears N 57 E, 67 lks. dist.  
 A fir 20" dia. bears S 58 E, 74 lks. dist.  
 A fir 4" dia. bears S 70 W, 28 lks. dist.  
 A fir 14" dia. bears N 44 W, 62 lks. dist.



Description of corner evidence found:

After much search and trying to many corners in the area, I determined there was a large error made between the  $\frac{1}{4}$  cor. common to Sections 28 & 29 being 2.73 chains longer than the original GLO calls. At this location I found the following evidence for this section corner as was described in the survey made by George S. Pershin during 1879:

A tamarack stump with BT scribed on its face bearing N 57 E, 67 lks. dist. from assumed corner location.

A fir stump with BT scribed on its face bearing S 70 W, 28 lks. dist. from assumed corner location.

A fir stump with BT scribed on its face bearing N 44 W, 62 lks. dist. from assumed corner location.

Description of monument and accessories established to perpetuate the original location of this corner:

Using the bearing trees as identified above, I located the position of the Section Corner and set a  $\frac{1}{2}$ " rebar in a mound of stone and painting the blazes of the stumps red and yellow and leaving a tag nailed to a young tree that describes the corner. Though new bearing trees are needed badly, I did not set any new trees.




Office of..... County of.....  
 State of..... I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by.....  
 (COUNTY OFFICIAL) (DEPUTY)

Q-722

R-9

History of original corner establishment:

Original survey was made by Wm. H. Odell, US Deputy Surveyor under contract No. 114 dated July 2, 1866. The section corner was set on Oct. 12, 1866.



A resurvey was made by George S. Pershin under Contract No. 332 dated July 29, 1879. The corner was again set on Aug. 25, 1879. He set the following bearing trees:  
A tamarack 4" dia. bears N 57 E, 67 lks. dist.  
A fir 20" dia. bears S 58 E, 74 lks. dist.  
A fir 4" dia. bears S 70 W, 28 lks. dist.  
A fir 14" dia. bears N 44 W, 62 lks. dist.

Description of corner evidence found:

After much search and trying to many corners in the area, I determined there was a large error made between the 1/4 cor. common to Sections 28 & 29 being 2.73 chains longer than the original GLO calls. At this location I found the following evidence for this section corner as was described in the survey made by George S. Pershin during 1879:  
A tamarack stump with BT scribed on its face bearing N 57 E, 67 lks. dist. from assumed corner location.

A fir stump with BT scribed on its face bearing S 70 W, 28 lks. dist. from assumed corner location.

A fir stump with BT scribed on its face bearing N 44 W, 62 lks. dist. from assumed corner location.

Description of monument and accessories established to perpetuate the original location of this corner:

Using the bearing trees as identified above, I located the position of the Section Corner and set a 1/2" rebar in a mound of stone and painting the blazes of the stumps red and yellow and leaving a tag nailed to a young tree that describes the corner. Though new bearing trees are needed badly, I did not set any new trees.



Office of..... County of.....  
 State of..... I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 by..... (COUNTY OFFICIAL) (DEPUTY)

Q-722