



NW Corner of the SW 1/4 of the SW 1/4
 Sec. 2, T2N, R32 E
 find 1" iron pin in concrete

Plot of Terrace Park Add'n information -
 the W 1/4 of Sec. 2 and the NW corner
 of Sec 2 were not found. Plat infor-
 mation was best information available.

Notes:
 1. Bearings and pin information based on
 Kent W. Cox. Survey dated 10-1-70. Umatilla
 County survey # C-16-A.
 2. (recorded distances)

- denotes set 5/8" iron pins w/ aluminum caps
- denotes found 1/2" iron pins

RECEIVED BY
 Umatilla County Surveyor
 Date 5-1-80
 Rec'd By [Signature]
 No. R-91-B

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
 David H. Krumbein
 OREGON
 JULY 17, 1976
 DAVID H. KRUMBEIN
 933

KRUMBEIN ENGINEERING CO. ENGINEERS - SURVEYORS - PLANNERS 221 S. Main, Pendleton, Oregon	SCALE 1" = 50'
	DATE 5-3-79
	DRN. BY M.L.J.
	CHK. BY D.H.K.
Survey for STEVE COREY Block 9 & 10, Terrace Park Addition to City of Pendleton, Oregon	DRNG. NO. 79-31C