

OREGON CORNER RESTORATION FORM

Section 25 Township 1 N Range 33 E W

County Umatilla Date 30 October 2004

T-23

CORNER DESIGNATION

Center One Quarter

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_


None

Monument(s) & Accessories Found: (Condition and Source)

Fence Line North, Fence posts East-West

Monument Detail

Sketch



2 1/2" BRASS CAP  
ON 1 1/2" X 30"  
IRON PIPE

Monument Set (Procedures and Description)

Brass Cap set at Fence Intersection, verified dimensions as indicated on survey map.

New Accessories

Set 5/8" X 30" iron Rebar w/ Alum Cap stamped PLS 933,  
North 28.7 Feet, East 32.6 Feet, West 21.86 Feet and S 15°E  
12.7 feet swt 1/2" X 36" Iron Rebar, no cap.

Location & Comments

Section 25 is 1 1/2 miles \_\_\_\_\_  
South of Spring Cr. Rd. \_\_\_\_\_

Surveyor's Seal

Firm/Agency \_\_\_\_\_

Krumbein Engineering

Address 361 S.E. 2nd  
Pendleton, OR. 97801

Party Chief Dave Krumbein

Notes \_\_\_\_\_

Witness \_\_\_\_\_



RENEWS 6/30/05