

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/02/02

CORNER DESIGNATION: 2N32P17, The East Quarter Corner of Section 22.

PREVIOUS RENEWALS/ SURVEYS, ETC.:

Most recent Umatilla County Surveyors Corner Record: 93-54-C.

MONUMENT AND ACCESSORIES FOUND:

Found 2 1/2" brass cap on galvanized iron pipe monument with cap buried 2" below ground level, marked as shown in monument marking detail. Per corner record, all accessories are intact.

MONUMENT MARKING DETAIL:

T2N R32E
1/4
S22 | S23
1993
PLS 1106

LOCATION & COMMENTS:

Corner monument falls at East edge of field road at projection of fences South and East.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 723414.03
E = 8640309.20

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N32P17

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

05

05
26
05

Karen A. Nevens

RECEIVED BY

Umatilla County Surveyors
Date 2-02
Rec'd By KK
No. 02-43-9