

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 12/31/01

CORNER DESIGNATION: 2N33, C-13, the East 1/4 Corner of Section 4.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Corner was reestablished by Dave Krumbein under Umatilla County Surveyor's Survey No. H-73-A.

MONUMENT AND ACCESSORIES FOUND:

Found a 2 1/2" brass cap on 2" galvanized iron pipe with cap protruding 16" from ground, marked as shown in monument marking detail. There is no corner record for the corner and no accessories.

MONUMENT MARKING DETAIL:

INDIAN
ALLOTMENT



LOCATION & COMMENTS:

Corner located about 15' West of a gravel driveway off Mission Highway, near top of steep dirt bank.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

N = 740030.26

E = 8666218.09

FIRM/AGENCY: William R. Wells, PLS
P.O. Box 1696
Pendleton, Oregon 97801

2N33C13

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Will. R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Rec'd By KK

No. 02-47-9