

PUBLIC LAND CORNER CONDITION REPORT

UMATILLA COUNTY, DATE: 01/23/02

CORNER DESIGNATION: 2N33T17, the East Quarter Corner of Section 27.

PREVIOUS RENEWALS/ SURVEYS, ETC..:

Most recent Umatilla County Surveyors recorded survey record: 92-11-B.

MONUMENT AND ACCESSORIES FOUND:

Found a 2" galvanized iron pipe bent badly and leaning at East edge of gravel drive. The cap is gone. Set hub at straight location of pipe for measure point. This is a witness corner monument, 30.00 feet East of true corner point. See Survey No. 92-11-B.

Corner needs to be remonumented and verified against nearby monuments reported on Survey No. 92-11-B.

MONUMENT MARKING DETAIL:

LOCATION & COMMENTS:

Located on East edge of gravel drive.

STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:

Witness corner monument 30 feet East of true corner point:

N = 718849.82

E = 8671966.36


True corner point:

N = 718849.13


E = 8671936.37

FIRM/AGENCY: William R. Wells
P.O. Box 1696
Pendleton, Oregon 97801

2N33T17



William R. Wells



renews 6-30-02

RECEIVED BY

Umatilla County Surveyor

Date 2-02

Count by KK

No. 02-43-9

J