

USDA-FOREST SERVICE

Index File No. J-~~A~~ 21

T 45 R. 30E

Merid. WILL

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. UKIAH

County UMATILLA


N.F. UMATILLA

State OREGON

Tract or Survey No. _____

Cor. No. _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

B. L. M. BRASS CAPPED IRDN PIPE PROPERLY STAMPED

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 45" POND. PINE N28°E, 134.6 FT.

A 36" POND. PINE S78°W, 38.5 FT.

A 23" POND. PINE N76°W, 54.1 FT.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

CORNER IS 30 FT. WEST OF ROAD 5308-242

Signature

Dennis L. Gaylord

Title

Division

PLS 1636

Headquarters

Date

11-22-83

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

NONE

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 12" POND, PINE BEARS S59°E, 165.7 FT. SCRIBED "T4S R30E S13 BT" ON A SINGLE BLAZE

Work Done By DENNIS L. GAYLORD Title LAND SURVEYOR Date NOV 14 '83 State Registration No. OREGON PLS 1636
or Agency

Certified Cor. Record Prepared ? (Yes) No Filed At: UMATILLA Co. SURV. OFF. Date

REMARKS

Index File No. J-12 T. 4S R. 30E M. W.M. Tract or Surv. No.

Index File No. J-21 CORNER RECORD (SEARCH) (Ref. FSM 7151.4) Tract or Survey No. _____ Cor. No. _____
 T 4 S. R. 30 E. R.D. Ukiah County Umatilla
 Merid. Willamette N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone mound, mound 2' diam., 10" above ground, fair condition. Cannot identify corner stone. There is a down post with an old location on it at the mound.

2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

There are four apparent B.T.'s. Only the one in SE quadrant has visible scribing. It is down and scribing is on the bottom side. The other 3 all have "Attention" (warning against destruction) signs. The trees in NW and NE quadrants have been chopped on, but cannot distinguish scribing. Blaze closed on tree in SW quadrant.
 (cont. in block 12)

3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Stone mound sets 10 ft. south of primitive road. Two B.T.'s are below road and two above.

4

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

7

PLANE COORDINATE POSITION DATA

State _____ Zone _____

 Estab. By _____
Agency

8

Signature
 T. Hollamon

Title
 Eng, Tech,

Division

Headquarters
 S.O.

Date
 5/31/74

7100-52-(3/68)

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed blank B.T. tags in all 4 apparent B.T.'s

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

There appears to be a comedy of errors with the B.T.'s. This has not been uncommon in this area. See diagram:

Note reversed distances and also the bearing noted as S.78°East occurs as S.78°W.

Index File No. T. R. M. Tract or Surv. No. Cor.