

T. 4 N., R. 28 E., W.M.

Chains		Feet
20.08	Set 2 x 4 ins. stake mkd. 1/16 as NE cor. SE $\frac{1}{4}$ NE $\frac{1}{4}$ .	
40.16	NE cor. sec. 10.	
<hr/> By lining in both ways with opposite 1/16 cors. I set 2 x 4 ins. stake mkd. 1/16 as center NE $\frac{1}{4}$ .		
Ran on line bet. NE cor. SE $\frac{1}{4}$ NE $\frac{1}{4}$ and NW cor. SW $\frac{1}{4}$ NE $\frac{1}{4}$ , N. 89° 55' W., above cors. being intervisible		
10.00	Set trial stake as SE cor. Farm Unit F on line.	
14.04	Set 2 x 2 ins. stake mkd. W C as witness cor. on line.	
15.68	Meander cor. center O. R. & N. track.	
17.49	Set 2 x 2 ins. stake on line mkd. W C as witness cor.	
20.00	Center NE $\frac{1}{4}$ .	
30.00	Set trial stake on line as SW cor. Farm Unit C.	
39.99	1/16 corner. I then set 2 x 2 ins. stake in position of trial stake as SE cor. Farm Unit F.	
Trial stake set as SW cor. Farm Unit C being in right position was replaced by 2 x 2 ins. stake.		
<hr/> The NW cor. NE $\frac{1}{4}$ NE $\frac{1}{4}$ being visible from SW cor. SE $\frac{1}{4}$ NE $\frac{1}{4}$ , ran		
N. 0° 29' E. bet. E $\frac{1}{2}$ and W $\frac{1}{2}$ of NE $\frac{1}{4}$ on line from SW cor. SE $\frac{1}{4}$ NE $\frac{1}{4}$ .		
10.00	Set trial flag on line to give direction to N. Bdy. of Farm Unit N	
20.07	Center NE $\frac{1}{4}$ .	
30.07	Set trial flag on line to give direction to N. Bdy. Farm Unit F	
40.14	1/16 cor. on sec. line. Reset trial flags on line in their proper positions, that is, 10.04 chs. from center of NE $\frac{1}{4}$	
<hr/> I then set flag on E. Bdy. of sec. on line and 10.04 chs. from NE cor. sec.		