

Subdivisional Lines, T 6 N R 32 E W M.

Chains	
40.40	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.80	The Cor. Land; gently rolling. Soil; 1st rate. Grass; good.
N. bet. Sees. 28 & 29. Var. 19°45' E.	
40.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for Cor. to Sees. 20, 21, 28 & 29. Drove pine stake, 2 ft. long, 2 ins. sq., in S.E. pit. Land; rolling. Soil; 1st rate. Grass; good.
E. on random line bet. Sees. 21 & 28.	
40.00	Set temp. $\frac{1}{4}$ Sec. Cor.
80.00	Intersect at Cor. W. on true line.
40.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.00	The Cor. Land; rolling. Soil; good.
N. bet. Sees. 20 & 21. Var. 21°30' E.	
40.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for Cor. to Sees. 16, 17, 20 & 21.