

GOVERNMENT CORNER RESTORATION FORM

Township 3N Range 29E Sec. 5/4 County UMATILLA
State OREGON Date July 19, 1991 No. C-9

Corner Designation

1/4 CORNER 55/54

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals

Monument(s) Found: (Condition and Source)

FOUND NO EVIDENCE OF THE BRASS
MONUMENT AS DESCRIBED ON THE
SURVEY COUNTY No. 5-158-C DUE
TO NEWLY CONSTRUCTED U.S. 395
IMPROVEMENTS.

NONE

Accessories Found:

NONE

REGISTERED
PLANNING
COMMISSION

RECEIVED BY

Umatilla County Surveyor

Date 9-91

Rec'd By KK

No. 91-61-B

UMATILLA COUNTY SURVEYOR

Received _____

Recorded _____

Survey Inst. No. _____

File No. _____