

FIELD NOTES.

On the survey of the Interior

Lines of Tp. 3 N R 40 E

Willamette Meridian,

Oregon, as surveyed by Frank W Campbell

U. S. Deputy Surveyor, under his Contract No. 507

dated June 28th 1884

Survey commenced August 6th 1884

Survey completed August 8th 1884

NAMES AND DUTIES OF ASSISTANTS.

....., Compassman.

Frank O Baird Chainman.

....., Chainman.

William J Welch, Chainman.

....., Chainman.

Thomas J McArthur, Axeman.

....., Axeman.

....., Flagman.



PRELIMINARY OATHS OF ASSISTANTS.

We, Frank C Baird

William J. Welch

do solemnly swear that we will faithfully execute the duties of Chain Carriers, that we will level the chain over even and uneven ground, and plumb the tally pins, either by sticking or dropping the same; that we will report the true distance to all notable objects, and the true length of all lines that we will assist in measuring, to the best of our skill and ability, and in accordance with the instructions given us in

the survey of the Oulerier

lines of Township

3 N R 40 E Willamette Meridian, Oregon.

Frank C Baird, Chainman.

William J Welch, Chainman.

_____, Chainman.

_____, Chainman.

Subscribed and sworn to before me, this 21st

day of April 1884

[SEAL.] H H Campbell
Notary Public

We, Thomas J McArthur

do solemnly swear that we will well and truly perform the duties of Axemen in the establishment of corners and other duties, according to instructions given us, and to the best of our skill and ability

in the survey of the Oulerier lines of

T 3 N R 40 E Willamette Meridian, Oregon.

Thomas J. McArthur, Axeman.

_____, Axeman.

Subscribed and sworn to before me, this 5th day

day of August 1884

[SEAL.] H. H. Campbell
Notary Public
for Oregon

INDEX.

Referring the Lines to the Pages of the Field Notes.

T. *3 North* R. *40 East* Will. Mer.

<i>18</i>	<i>20</i>	<i>23</i>	<i>25</i>	<i>27</i>	<i>30</i>	
6	5	4	3	2	I	<i>13</i>
7	8	9	10	11	12	<i>11</i>
18	17	16	15	14	13	<i>8</i>
19	20	21	22	23	24	<i>6</i>
30	29	28	27	26	25	<i>4</i>
31	32	33	34	35	36	<i>2</i>

Meanders of Page to

Meanders of Page to

16

North bdy

46

Outer^{er} of T. 3 North R. 40 East
 Willamette Meridian, Oregon.

From the corner to Tps
 3 and 4 N. Ranges 40 & 41
 E I ran ^{West} East on a ran-
 -down line, between said
 Townships, the Var. of my
 compass being $21^{\circ}45'$ E
 I set temporary half mile
 and wide corners at each
 40 and 80 chs. and find
 the township line 5 miles
 and 75 chs and 18 chs
 long - I intersected the
 corner to Township 3 & 4
 N Ranges 39 & 40 E at
 corner

August 7th 1884

From the corner to Township
 3 and 4 N Ranges 39 & 40 E
 which is a post 4 in
 square firmly set in
 the ground marked

North body

Centering of T. 3 North R. 40 East
Willamette Meridian, Oregon.

T. 4 N. S. 31 on NE
 R. 40 E. S. 6. on SE
 T. 3 N. S. 1 on SW
 R. 39 E. S. 36 on NW face
 with 6 notches on each edge
 from which
 A tamarack 8 in diam bears
 N 51° W 37 lks dist marked
 T. 4 N. R. 39 E. S. 36 B. S.
 A tamarack 8 in diam bears
 N 60° E 9 lks dist marked
 T. 4 N. R. 40 E. S. 31 B. S.
 A tamarack 8 in diam bears
 S 58° E 33 lks dist marked
 T. 3 N. R. 40 E. S. 6 B. S.
 a pine 12 in diam bears
 S 46° W 54 lks. dist. marked
 T. 3 N. R. 39 E. S. 0 B. S.

FINAL OATHS FOR SURVEYS.

A list of the names of the individuals employed by Frank
W Campbell, U. S. Deputy Surveyor, to assist in
 running, measuring and marking the lines and corners described in the foregoing field
 notes of the survey of the Outer
 lines of Township
& N R 40 East Willamette Meridian, Oregon,
 showing the respective capacities in which they acted:

- _____, Compassman.
- Frank C Baird, Chainman.
- _____, Chainman.
- William J Welch, Chainman.
- _____, Chainman.
- Thomas McArthur, Axeman.
- _____, Axeman.
- _____, Flagman.

FINAL OATHS OF ASSISTANTS.

We hereby certify that we assisted Frank W.
Campbell, U. S. Deputy Surveyor, in surveying all
 those parts or portions of the Outer line
 of Township
& N R 40 East Willamette Meridian, Oregon,
 as are represented in the foregoing field notes as having been surveyed by him and under
 his direction; and that said survey has been, in all respects, to the best of our knowledge
 and belief, well and faithfully surveyed, and the corner monuments established, according
 to the instructions furnished by the U. S. Surveyor General of Oregon.

- _____, Compassman.
- Frank C Baird, Chainman.
- William J Welch, Chainman.
- _____, Chainman.
- _____, Chainman.
- Thomas J. McArthur, Axeman.
- _____, Axeman.
- _____, Flagman.

Subscribed and sworn to before me, this 1st day of Nov. 1884

[SEAL]

H. H. Campbell
 Notary Public
 for Oregon

FINAL OATH OF DEPUTY SURVEYOR.

I, Frank W. Campbell

United States Deputy Surveyor, do solemnly swear that in pursuance of

instructions received from James C. Tolman

U. S. Surveyor General for Oregon, bearing date of the 28th

day of June, 1884, I have well, faith-

fully and truly, in my own proper person, and in strict conformity with the instructions furnished by the U. S. Surveyor General for Oregon, the Surveying Manual, and the Laws of the United States, surveying all those

parts or portions of the Exterior line
of Township 3 N R 40 E

Willamette Meridian, in the State of Oregon, as are represented in the foregoing Field Notes as having been surveyed by me and under my directions; and I do further solemnly swear that all the corners of said survey have been established and perpetuated in strict accordance with the Surveying Manual, Printed Instructions, the Special Written Instructions of the U. S. Surveyor General for Oregon, and in the specific manner described in the Field Notes, and that the foregoing are the true Field Notes of such survey, and should any fraud be detected I will suffer the penalty of perjury under the provisions of an Act of Congress approved August 8th, 1846.

F. W. Campbell

U. S. Deputy Surveyor.

Subscribed and sworn to before me, this 28th

day of Nov
November 1884

H. W. Campbell

Notary Public

OFFICE U. S. SURVEYOR GENERAL,

Portland, Oregon, *Feb 4, 1885*

The following Field Notes of the Survey of the

Eastern lines of Township
3 North Range 40 East
Willbey Oregon

executed by *Frank W. Campbell*

under his Contract No. *507*, dated *June*

28th 188*4*, having been critically examined,

the necessary corrections and explanations made, the said

Field Notes and the survey they describe are hereby approved.

James C. Tolman
 Surveyor General.