

| | |
|-----------------|--|
| Chains 76.35 | <p>The corner to Secs. 5, 6, 7 & 8.</p> <p>Land, gently rolling.</p> <p>Soil, 1st rate and sandy.</p> <p>Sept. 29th, 1859.</p> |
| | <p>North between Secs. 5 & 6 on random line.</p> <p style="text-align: right;">Variation 20° 15' East.</p> |
| 40.00 | Set post for temp. 1/4 Sec. corner. |
| 80.50 | <p>Intersect North boundary 70 links East of Sec. corner.</p> <p>S. 30' East on true line between Secs. 5 & 6.</p> |
| 40.50 | Set post for 1/4 Sec. corner in mound of earth &c., as per instructions. |
| 80.50 | <p>The corner to Secs. 5, 6, 7 & 8.</p> <p>Land, level.</p> <p>Soil, 1st rate.</p> |

General description.

The quality of land in this Township is 1st and 2nd rate prairie level or gently rolling.

Butter Creek, which runs through the western portion of the Township is a stream of clear color water about 20 links wide on which is considerable rich bottom land.

This Township is destitute of timber.