

Exterior Bdy. of T. 4 N., R. 36 E., W.M. (E. Bdy.)

Chains		Feet
	N. on E. Bdy. of Sec. 12	
	Var. 21° E.	
40.00	Set post Cor. for $\frac{1}{4}$ Sec. on hill side facing the E.; made stone mound as per instructions.	
65.00	Creek, 5 lks. wide, course N.W.	
80.00	Set post Cor. for Secs. 1, 12, 6 & 7; made stone mound as per instructions.	
	Land; broken	
	Soil; 2nd rate.	
<hr/>		
	N. on E. Bdy. of Sec. 1	
	Var. 21° E.	
40.00	Set post Cor. for $\frac{1}{4}$ Sec.; made stone mound as per instructions.	
68.35	Intersected first Standard Parallel, 12.90 Chs. W. of T. Cor. for T 5 N., Rg. 36 & 37.	
	Made Closing Cor. for T. 4 N., Rs. 36 & 37, and Secs. 1 & 6. Made stone mound as per instructions.	
	Land broken	
	Soil: 2nd rate.	
	This Tp. contains considerable amount of First rate timbered lands, and some good agricultural lands.	
	The Tp. should therefore be subdivided.	
	Oct. 4th 1866.	
<hr/>		
	Subdivisional Lines of T 4 N R 36 E., W.M. As surveyed by same surveyor and Contract and date.	
<hr/>		
	Commence at post Cor. for Secs. 1, 2, 35 & 36 on S. Bdy. of Tp. thence	
	N. bet. Secs. 35 & 36	
15.00	Pine Creek, channel dry, course W.	
40.00	Set post Cor. for $\frac{1}{4}$ Sec. from which	
	A Pine, 30 ins. diam. brs. N. 89° W., 115 lks.	
	A Pine, 36 ins. diam. brs. S. 300 lks.	
80.00	Set post Cor. for Secs. 25, 26, 35 & 36, from which	
	A fir, 24 ins. diam. brs. N. 40° W., 22 lks.	