

Subdivisional Lines, T 5 N R 31 E W M.

Chains	
	as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.00	Drove charred stake & raised mound, with pits, etc., as per instructions, for Cor. to Secs. 10, 11, 14 & 15. Drove alder stake, 2 ft. long, 2 ins. sq., in S.E. pit. Land; rolling. Soil; 1st rate, good grass.
	E. on random line bet. Secs. 11 & 14.
40.00	Set temp. $\frac{1}{4}$ Sec. Cor.
80.24	Intersect N. & S. line, 203 lks. N. of Cor. N.88°33' W. on true line.
40.12	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.24	The Cor. Land; rolling. Soil; 1st rate, good grass.
	N. bet. Secs. 10 & 11. Var. 21°15'E.
40.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
80.00	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for Cor. to Secs. 2, 3, 10 & 11. Drove alder stake, 2 ft. long, 2 ins. sq., in S.E. pit. Land; rolling. Soil; 1st rate, good grass.
	E. on random line bet. Secs. 2 & 11.
40.00	Set temp. $\frac{1}{4}$ Sec. Cor.
79.95	Intersect N. & S. line, 233 lks. N. of Cor. N.88°20' W. on true line.
39.97	Drove charred stake & raised mound of earth, with pits, etc., as per instructions, for $\frac{1}{4}$ Sec. Cor.
79.95	The Cor. Land; rolling. Soil; 1st rate, good grass.