

OREGON CORNER RESTORATION FORM

Section 21 Township 1N Range 32E
County Umatilla Date: July 9, 2009

Corner Designation: 1N32R11

Quarter corner common to sections 21 and 28,
T1N, R32E, W.M., Umatilla County, Oregon.


Previous Renewals / Surveys, etc.

Corner originally set by Daniel Chaplin under contract no. 107 dated September 21, 1864.
His record reads: Set stone, 18 x 12 x 6 ins., for 1/4 sec. cor. William R. Wells in record of
survey 06-528-C states: Set brass cap.

Monument and Accessories found: (condition and source)
I found the brass cap by Wells in good condition as described.

Condition Report Only
 Not found
 Remonumented
 Unrecorded
 Surveyed in
 Referenced out

DIAGRAM



SKETCH

MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)
None. I held the monument by Wells. This certificate is being filed to report the state plane
coordinates given below.

For references:

The monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments
NAD 83/1991 State Plane Coordinate
Oregon North Zone
N = 688,965.69 ift
E = 8,633,041.33 ift

Compass Declination

Surveyors Seal

RECEIVED BY:
Umatilla County Surveyor
Date: 6-10
Rec'd By: RK
No. 10-93-C

Firm / Agency
Witness Tree Surveying
Address
P.O. Box G
Pilot Rock, Or. 97868
Party Chief
Stephen K, Haddock

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Stephen K. Haddock

OREGON
JULY 9, 2001
STEPHEN K. HADDOCK
56295LS

RENEWAL DATE 6-30-11