

Index
File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. U. I. R. Cor. No. 44 M


T 1N R. 35E

R.D. WALLAWALLA County UMATILLA

Merid. WILL

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

LARGE BOULDER IN PLACE PLAINLY MARKED "+" ON TOP & "U R" ON WEST FACE & "44 M" ON NORTH FACE.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 36" PINE IS NOW A SAWN & DECAYED STUMP - NO MARKS REMAIN - BEARS N72°30'W, 125 LINKS. ORIG. 5" NOW 18" FIR (DOUGLAS) BEARS S30°W, 169 LINKS. HAS HEALED BLAZE. PUT BT SIGNS ON BOTH.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

IN FENCE LINE 1/4 MILE S20°W OF ROAD 020 ALONG RES. BDRY.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Dennis L. Gayland Title _____ Division PLS 1636 Headquarters 50 Date 8-29-89 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

11

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13