

**PUBLIC LAND CORNER CONDITION REPORT**

**UMATILLA COUNTY, DATE:** 01/25/02

**CORNER DESIGNATION:** 2N32A15, The North 1/4 Corner of Section 3.

**PREVIOUS RENEWALS/ SURVEYS, ETC..:**

Most recent Umatilla County Surveyors recorded corner record: 88-19-C.

**MONUMENT AND ACCESSORIES FOUND:**

Found a 2 1/2" brass cap, 20" below ground in a farmed field, marked as shown in monument marking detail.

As per corner record, accessories are intact.

**MONUMENT MARKING DETAIL:**

T3N R32E  
1/4 S34  
S3  
T2N R32E  
1988  
PLS 1106

**LOCATION & COMMENTS:**

In a farmed field.

**STATE PLANE COORDINATE, OREGON NORTH ZONE, NAD83/91, INT. FOOT:**

N = 741885.01  
E = 8637181.92

**FIRM/AGENCY:** William R. Wells  
P.O. Box 1696  
Pendleton, Oregon 97801

2N32A15

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

*renews 6/30/02*

**RECEIVED BY**

Umatilla County Surveyor

Date 5-02

Rec'd By KK

No. 02-107-9

05  
26  
05

*From A. Norman*