

ORIGIN PUBLIC LAND CORNER REPORT / RESTORATION REPO.
Umatilla County Surveyor's Office

SECTION 17 and 20	TOWNSHIP 3N	RANGE 36E
COUNTY: Umatilla		DATE 6/20/08
CORNER DESIGNATION: N-6 West 1/16 corner common to sections 17 and 20		(Please check one)
		<input checked="" type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Renewed
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Surveyed In
		<input type="checkbox"/> Referenced Out
Previous Renewals / Surveys, etc. U.S. Indian Services Surveyor C.E. Redfield, set an Iron Post in 1919		
Monument(s) & Accessories Found: (Condition & Source) Found a 2" galvanized Iron Pipe with a 2 1/2" Brass Cap set in a Stone Mound at a fence corner. Fence runs East and South		
Monument Detail:	Sketch:	
Monument Set (Procedures and Description):		
New Accessories:		
Location & Comments: Corner is on a Knoll at the Southeast edge of a cleared field. A fence runs East and South from this corner.		Compass Declination:
Firm / Agency USKH Address: 5 N. Colville St., Walla Walla, Wa 99632		SURVEYOR'S SEAL OREGON JUNE 30, 1997 GREG E. FLOWERS 02820LS RENEWS 12/31/09 6/30/08
Party Chief Greg E. Flowers		
Notes		
Witness Damon Locke		

08-112-c