

USDA-FOREST SERVICE

Index File No. V-9
 T 3N R. 38E
 Merid. WILLAMETTE

CORNER RECORD (SEARCH)


(Ref. FSM 7151.4)

Tract or Survey No. _____
 Cor. No. _____

R.D. WALLA WALLA County UMATILLA
 N.F. UMATILLA State OREGON

CORNER DIAGRAM

T3N R38E



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 5" LARCH IS A SAWN STUMP. I OPEN TO REVEAL SCRIBED "T". BEARS $542^{\circ}W$, 10LKS.
 ORIG. 4" LARCH IS A SAWN STUMP 3' HIGH WITH HEALED LOWER BLAZE. BEARS $N62^{\circ}W$, 11LKS.
 ORIG. 4" PINE IS A ROOT CROWN. BEARS $S31^{\circ}E$, 5LKS. ORIG. 3" PINE TONE IS GONE.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

AT OLD CORNER SET IN 1899 ($N10^{\circ}W$, 534LKS) I FIND A 14" SAWN LARCH STUMP (ORIG. 4") WITH AXE MARKS ON FACE & SOME SCRIBES. THIS TREE WAS $N45^{\circ}E$, 2 LKS FROM OLD CORNER. THE OTHER 3 BT'S AT THIS OLD CORNER ARE GONE. IN CLEARCUT WEST OF ROAD 3100-326

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Dennis H. Layford

PLS 1636

Sept 5, 1997

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I PUT BT SIGNS ON THE TWO LARCH STUMPS AT THE CORNER AND ALSO A BT SIGN ON THE OLD SUPERCEDED CORNER LARCH STUMP.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.

V-9 T3N R38E