

GOVERNMENT CORNER RESTORATION FORM

Township 3N Range 29E Sec. 54 County UMATILLA
 State OREGON Date July 19, 1991 No. A-9

Corner Designation

SECTION CORNER $\frac{32}{5} | \frac{33}{4}$


- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

MONUMENT DETAIL

Previous Renewals


Monument(s) Found: (Condition and Source)

FOUND A 2 1/2" Ø BRASS CAP IN WATER
 VALVE BOX FLUSH WITH ASPHALT
 AT INTERSECTION OF EDWARDS ROAD
 AND BALL AVENUE IN GOOD CONDITION
 MARKED AS SHOWN




Accessories Found:

1) FOUND WITNESS CORNER 2 1/2" Ø BRASS CAP ON 1 1/2" Ø GALV. IRON PIPE
 WITH WITNESS SIGN AND POST NW 38.05 FEET



2) FOUND WITNESS CORNER, 2 1/2" Ø BRASS CAP ON
 1 1/2" Ø GALV. IRON PIPE WITH WITNESS SIGN AND POST
 SW 35.04 FEET



REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

UMATILLA COUNTY SURVEYOR

Received _____

Recorded _____

Survey Inst. No. _____

File No. _____

RECEIVED BY
 Umatilla County Surveyor
 Date 9-91
 Rec'd By KK
 No. 91-101-R