

USDA-FOREST SERVICE

Index File No. 0-20

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 45 R. 30E

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



T45 R30E

NE 1/16 S 23

1981

PLS 848

DESCRIBE CORNER MONUMENT FOUND

Corner not previously established.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

N/A

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner can be reached by following a road Northerly approx. 3/8 mi. from the ridge road, near the center 1/4 Sec. 23, then walking approx. 1500 ft. East to the corner. Corner is on an East slope.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estob. By _____
Agency

Signature

Title PLS 848 Division _____ Headquarters Mt. Vernon, OR Date 8/12/81
 7100-52-(3:68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 3"x30" galv. iron pipe with 3" brass cap stamped as shown on the diagram, set 20 in. in the ground.

From which:

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A pine 10 in. dia. bears N48°E, 6.8 ft. scribed NE 1/16 S 23 BT.
A pine 9 in. dia. bears S57°W, 12.4 ft. scribed NE 1/16 S 23 BT.
Set steel post with warning and boundary signs 5 ft. North and 5 ft. West from corner. Nailed bearing tree signs and brass washers stamped PLS 848 to each tree. Painted red band around each tree.

Work Done By D.M. Ferguson Title Surveyor Date 8/12/81 State Registration No. or Agency OR PLS 848

Certified ~~REGISTERED~~ ~~RECORDED~~ Expired? Yes No Filed At: Umatilla Co. Surv. Office Date 10/81

**PROFESSIONAL
LAND SURVEYOR**

REMARKS

Witnesses to above corner:

D. Mitchell Ferguson
Mike Woodward

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848