


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously set.



Q-20

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 3"x30" galv. iron pipe with 3" brass cap, stamped as shown on the diagram. Set 12 in. in the ground and raised a mound of stone around the pipe.  
From which:  
A pine 14" dia. bears S63° 45' W, 196.0 ft. scribed SE 1/16 S 23 BT.  
No other trees available.  
Set steel posts with warning and boundary signs 10 ft. South and 10 ft. West from corner. Nailed bearing tree sign and brass washer stamped PLS 848 to tree. Painted a red band around the tree.

I hereby certify that the above corner monument was established on 7/27/81 as herein described.

Witnesses:

\_\_\_\_\_  
D. Mitchell Ferguson

\_\_\_\_\_  
Mike Woodward

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Douglas M. Ferguson*  
OREGON  
JULY 12, 1909  
DOUGLAS M. FERGUSON  
848

Office of... Co. Surveyor..... County of..... Umatilla.....  
State of... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the... 7<sup>th</sup> day of... January... 1982  
..... David Humble..... by... Betty Shotts.....  
(COUNTY OFFICIAL) (DEPUTY)

82-02-6

T-2