

USDA-FOREST SERVICE

Index

File No. T-17

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. \_\_\_\_\_

Cor.

No. \_\_\_\_\_

T 4S

R. 30E

R.D. Ukish

County Umatilla

Merid. W.M.

N.F. Umatilla

State Or.

CORNER DIAGRAM



T4S R30E

$\frac{1}{4}$

S27 | S26

DESCRIBE CORNER MONUMENT FOUND

Stone 18"x7"x8" mkd:  $\frac{1}{4}$

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. 380-78

Filed At. S.O.

Object Ident. trees

Ident. By F.S. Munro  
Signature

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_  
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls at Sly. end of flat open meadow in N-S fence line. Go S.  $\frac{1}{8}$  mi. along posted property line from NE cor. S27.

Signature

F.S. Munro

Title

L.S.

Division

Headquarters

Date

9/26/84

7100-52-(3,68)

5

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

2 1/2" x 30" alum. pipe with 3" alum. cap mkd:

Bury orig. stone alongside.  
Build stone mound around mon.

T4S R30E

1/4  
S27 1/2 S26  
PLS 1832  
1984

**ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

P. pine, 10", N55 1/8° E, 92.5 ft.  
P. pine, 13", N22-3/4° W, 26.3 ft.

BTs have reqd. paint, tags & signs.

Work Done By F.S. Munro Title L.S. Date 9/18/88 State Registration No. 1832  
or Agency

Certified Cor. Record Prepared ? Yes  No  Filed At: Umatilla Co. Surveyor Date \_\_\_\_\_

REMARKS

Index

File No. T-17

**CORNER RECORD (SEARCH)**

(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_

Cor. No. \_\_\_\_\_

4-110


T 4 S. R. 30 E.

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

**CORNER DIAGRAM**



**DESCRIBE CORNER MONUMENT FOUND**

(1 FT.)

Stone mound, 4' diam., 1' deep, 1' above ground, fair condition.

Noevisible markings. Mound appears to be man-made.

2

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

None.

There were no original B.T.'s None were available.

6

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

7

**PLANE COORDINATE POSITION DATA**

State \_\_\_\_\_ Zone \_\_\_\_\_

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

8

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER**

Mound sets near top of hogback in stand of scattered second growth p. pine approx. 16 ft. west of north-south fence (Forest boundary). It is approx. 200 ft. north of edge of mature timber stand. There is evidence of line blazing on the north-south line from mound. There is a primitive road about 500 ft. west.

3

4

Signature

5/8/74

Title

Eng. Tech,

Division

Headquarters

S.O,

Date

5/8/74

7100-52-(3/68)

5

T

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I placed a location poster on a 12" p. pine in S.W. edge of mound and another on a fence post 16 ft. east. I engraved "Assumed  $\frac{1}{4}$  corner" on each.

Work Done By \_\_\_\_\_ Title \_\_\_\_\_ Date \_\_\_\_\_ State Registration No. or Agency \_\_\_\_\_

Certified Cor. Record Prepared ? Yes No Filed At \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.