

USDA-FOREST SERVICE

Index
File No. V-17

T 45 R. 33E

Merid. Willamette

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)


R.D. Ukiah County Umatilla

N.F. Umatilla State Oregon

Tract or Survey No. _____
Cor. No. Sec

CORNER DIAGRAM

T45 R33E



DESCRIBE CORNER MONUMENT FOUND

None - falls in roadway

Iron Post 2 1/2" dia. with Brass Cap stamped T45 R33E

S 27 RM 1977 with arrow, sets 6 ins above ground 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Iron Post 2 1/2" dia with Brass Cap stamped T45 R33 E

S 26 RM 1977 with arrow, sets 5 ins. above ground

A Pine 10 ins dia. bears N 63 1/2° E, 67 IKs S 26 BT

A Fir 16 ins dia. bears S 48° E 76 IKs S 35 BT

A Fir 13 ins dia. bears S 21 W 83 1/2 IKs S 34 BT 3

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Jet of Ukiah - Hilgard Hwy 244 & Rd 54
go East 0.3 mi to Forest road on left, go up hill
past S 1/6 S 34/35 and 1/4 34/35 along road
1.2 mile to corner on left

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature
D. Kulber

Title
PLS 933

Division

Headquarters

Date

8/84

7100-52 (3-68)

4

5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By D. Krumbin Title Surveyor Date 8/04 State Registration No. PLS 933
or Agency

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. V-17 T. 4S R. 33E M. Willamette Tract or Surv. No.

Cor. Sec