

USDA-FOREST SERVICE

Index

File No. X-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. 1/4

T 4S R. 33E

R.D. Ukiah


County UMATILLA

Merid. Willamette

N.F. UMATILLA

State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found a 3" diameter BLM B.C. dated 1977 with a Steel fence Post with SIGNS # 54-4

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A 20" dia. Pine bears N 84°E 33 LINKS
 A 11" dia. Pine bears S 36°W 52 LINKS

Trees have SIGNS # 54-3 and # 54-4

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From Jct. of Ukiah Hillgard Highway and Forest Road 54, Go N on Rd 54 0.4 mi. Park Truck and walk uphill 150' to corner

Signature

David H. Kline

Title

PLS 933

Division

Headquarters

Date

6-83

7100-52 (3-68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Painted Trees

Work Done By D. Krumbein Title Surveyor Date 6-83 State Registration No. PLS 933
or Agency

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. X-13 T. 45 R. 33E M. Willamette Tract or Surv. No.

Cor. 1/4