

**OREGON CORNER RESTORATION FORM**

N - 23

SECTION 13, TOWNSHIP 5 NORTH, RANGE 27 EAST,  
WILLAMETTE MERIDIAN

COUNTY : UMATILLA      DATE : JULY 2014

PUBLIC LAND CORNER :  
SOUTH QUARTER CORNER, SECTION 13

- CONDITION REPORT ONLY
- NOT FOUND **\*\*DESTROYED\*\***
- RECOVERY
- REMONUMENTATION
- REFERENCED

**PREVIOUS ACTIVITY**

THIS CORNER WAS REMONUMENTED AND REFERENCED  
DURING COUNTY SURVEY 06-461-B

**MONUMENT FOUND :**

NONE

**MONUMENT DETAIL :**

**DESTROYED  
BY FARMING  
ACTIVITY**

**REFERENCES / ACCESSORIES :**

FOUR REFERENCES, PER CORNER RESTORATION FORM N23-06-461-B, APPEAR  
TO BE UNDISTURBED. THEIR REFERENCE POSITIONS WERE PREVIOUSLY  
REPORTED AS FOLLOWS:

- AN ALUMINUM TAG "PLS LS 48490" ON A FENCE POST LIES N71°30'E, 164.96 FEET
- A 5/8 INCH IRON REBAR WITH YELLOW PLASTIC CAP MKD: "PLS LS 48490" LIES N41°E, 68.34 FEET
- A 5/8 INCH IRON REBAR WITH YELLOW PLASTIC CAP MKD: "PLS LS 48490" LIES N20°W, 50.80 FEET
- A 5/8 INCH IRON REBAR WITH YELLOW PLASTIC CAP MKD: "PLS LS 48490" LIES N72°30'W, 127.86 FEET

**RECEIVED BY**

Umatilla County Surveyor  
Date: 8/15/2014  
Rec'd By: [Signature]  
No.: 14-113-R

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Rodney J. Lewis*

OREGON  
JULY 14, 1998  
**RODNEY J. LEWIS**  
2872

EXPIRES 12-31-14