

Index
File No. L-13

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____


T 5 S. R. 30 E.

R.D. Ukiah County Umatilla

Merid. Will.

N.F. Umatilla State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Stone 20"X15"X10", 15" above ground, marked 1/4, and in good condition.

Monumented By BLM in 1978

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

18" D.B.H. Pond. pine for sec. 15 in poor cond. also found metal posters.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

ON 9-18-73 I Placed a Location Poster (F.S. Number 54-5 [9-64] ON a 22" Ponderosa Pine APPROX. 50 feet East of E on F.S. Road Number S-420.

T.G. Hollaman

Signature
Melvin Christian

Title

Division

Headquarters
Ukiah

Date

5-22-73

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ **Title** _____ **Date** _____ **State Registration No. or Agency** _____

Certified Cor. Record Prepared ? Yes No **Filed At:** _____ **Date** _____ 11

REMARKS

12

Index File No. L-13 **T.** _____ **R.** _____ **M.** _____ **Tract or Surv. No.** _____ **Cor.** _____ 13

Index File No. L-13

CORNER RECORD (SEARCH)

Tract or Survey No. _____ Cor. No. _____


T 5 S. R. 30 E.

R.D. UKIAH County Umatilla

Merid. Will.

N.F. Umatilla State ORE.

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Basalt stone 14" x 10" x 4", 4" Above ground and in good condition, is marked $\frac{1}{4}$ Monumented By BLM in 1978 ²

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

14" D.B.H. pine brs. S. 81° W. 42 lks. - in good cond.
38" D.B.H. pine brs. N. 16° E. 21 lks. - FAIR VIGOR

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____ ⁷

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____ ⁸

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER ³

See other card, some discrepancy here, T&H. 2/75

Signature

Title

Division

Headquarters

Date

7100-52 ⁴

Don McCullough

Forestry Tech.

UKIAH

8-31-66

REV. '65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. _____
or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File No. L-13 T. R. M. Tract or Surv. No. Cor. _____