


USDA-FOREST SERVICE

Index
File No. U-21
T 58 R. 30E
Merid. W.M.

CORNER RECORD (SEARCH)

N. Fk. (Ref. FSM 7151.4)
R.D. John Day County Umatilla
N.F. Umatilla State Or.
Tract or Survey No. _____
Cor. No. _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Cor. falls on SEly slope, W. of fence and N. of Cr.
Follow posted line from sect. cor. to south.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature
F.L. Munro

Title
PLS

Division

Headquarters

Date
6/4/90

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

2 1/2" alum. pipe with 2 1/2" alum. cap mkd.:

S1/16
S26 | S25
PLS 1832
1990

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

P. Pine, 13", S37°E, 20.4'; mkd.: S1/16 S25 BT
 P. Pine, 12", S33 1/4°W, 40.4'; mkd.: S1/16 S26 BT
 BTs have red blaze, band; BT tags, 54-9 signs and alum. "PLS 1832"
 washers. 6' fence post with 54-9 sign within 5' of cor.

10

Work Done By F.S. Munro Title PLS Date 5/16/90 State Registration No. 1832
 or Agency _____
 Certified Cor. Record Prepared ? Yes No _____ Filed At: Umatilla Co. Surveyor Date _____

11

REMARKS

12

Index File No. U-21 T. 58 R. 30E M. W.M. Tract or Surv. No. _____ Cor. _____

13