

USDA-FOREST SERVICE

Index  
File No. V-16

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. \_\_\_\_\_ Cor. No. \_\_\_\_\_

T 55 R. 32E

R.D. Ukiah County Umatilla

Merid. Willamette

N.F. Umatilla State Oregon

CORNER DIAGRAM



E 1/16  $\frac{S 27}{S 34}$   
1968

DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set,  
2½ ins. diam., in a mound of  
stone, 2½ ft. base, to top,  
with brass cap mkd,

U.S. Dept. of Interior  
Bureau of Land Management

E 1/16  $\frac{S 27}{S 34}$   
1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Douglas fir, 12 ins. diam., bears N. 36° E., 90 lks. dist.,  
A Ponderosa pine, 17 ins. diam., bears S. 2° E., 58 lks. dist.,  
BT's are alive with scribing visible on partially healed single  
blaze.

PHOTO IDENTIFICATION DATA

Photo No. \_\_\_\_\_  
Filed At. \_\_\_\_\_  
Object Ident. \_\_\_\_\_  
Ident. By \_\_\_\_\_  
*Signature*

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Corner of fences S and W bears South 7 feet.

PLANE COORDINATE POSITION DATA

State \_\_\_\_\_ Zone \_\_\_\_\_  
X \_\_\_\_\_  
Y \_\_\_\_\_  
Estab. By \_\_\_\_\_  
*Agency*

Title  
LS 1099

Division

Headquarters

Date  
9-17-84

7100-52-(3,68)

*Signature*  
*Jay A. Angley*

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Gary Langlitz Title Land Surveyor Date 8-84 State Registration No. 1099  
or Agency

Certified Cor. Record Prepared? Yes  No Filed At: \_\_\_\_\_ Date \_\_\_\_\_

REMARKS

Index File No. V-16 T. 5S R. 32E M. Willamette Tract or Surv. No. \_\_\_\_\_ Cor. \_\_\_\_\_