

Index
File No. V-7
T 55 R. 32E
Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____
R.D. UKIAH County UMATILLA
N.F. UMATILLA State OREGON

CORNER DIAGRAM

T 5 S R 32 E
 S 29
 S 32
 1968

DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set,
2½ ins. diam., in a mound of
stone, 2½ ft. base, to top,
with brass cap mkd.

U.S. Dept. of Interior
Bureau of Land Management

T 5 S R 32 E
 S 29
 S 32
 1968

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Ponderosa Pine, 20 ins. diam., bears S. 31° W., 115 lks. dist.,
with healed blaze. (Orig. BT).
A Larch, 22 ins. diam., bears N. 83° E., 138 lks. dist., alive
with well-healed blaze.

PHOTO IDENTIFICATION DATA

Photo No. 280-293
Filed At. UMATILLA NAT FOR
Object Ident. SUB STA
Ident. By Ray Jangit

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Ray Jangit Agency _____

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

10

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

11

REMARKS

12

Index File No. V-7 T. 55 R. 32E M. WILLAMETE Tract or Surv. No.

Cor: 13