

Index
File No. X-10

CORNER RECORD (SEARCH)

(Ref. FSM 7.151.4)

Tract or
Survey No. _____
Cor.
No. _____


T 55 R. 32E

R.D. UKIAN County UMATILLA

Merid. WILLAMETTE

N.F. UMATILLA State OREGON


CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found an iron pipe, firmly set,
2½ ins. diam., with brass cap
mkd.

U.S. Dept. of The Interior
Bureau of Land Management



DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

A Douglas Fir, 14 ins. diam., bears N. 72½°E., 12 lks. dist.,
A Douglas Fir, 13 ins. diam., bears S. 3° W., 10½ lks. dist.,
BT's in good condition with scribing visible on unhealed single
blaze.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency
Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Title LS 1099 Division _____ Headquarters _____ Date 9-17-64 FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

None

ACCESSORIES: DESCRIBE NEW OBJECTS WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

None

Work Done By Gary Langlitz Title LS 1099 Date 8-84 State Registration No. or Agency

Certified Cor. Record Prepared? Yes No Filed At: Date

REMARKS

Index File No. X-10 T. 55 R. 32 E M. WILLAMETTE Tract or Surv. No. Cor. 13