

USDA-FOREST SERVICE

Index File No. D-13


CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. _____

T 6S. R. 30 E R.D. Ukiah County Umatilla

Merid. Willamette N.F. Umatilla State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None
Set brass cap

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____

Signature _____ 7

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____

Agency _____ 8

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the intersection of U.S. Forest Road 419N and 537N, go East along 537N 3.3 miles, then go West 1.8 Miles, then go North 0.3 miles, and corner is Northeast about 700 ft. from Road.

Signature *David H. Miles*

Title CORNER DIVISION (1) Headquarters (1)
OPLS 933

Date 7-77 7100-52-(3/68) 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" iron pipe with brass cap.
 Pipe is 26" in ground.
 Mound of stone to cap.

T. 6S., R. 30E.

S. 1/16

S.4

S.3

1977

PLS 933

Stamped:

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 13" pine bears N. 45° W. 29.7 ft.
 A 12" fir bears S. 74° E. 40.2 ft.

Set steel fence post 2' West of brass cap w/sign.
 Painted red band around bearing tree w/sign.

10

Work Done By T. Hamby Title Party Chief Date 6/23/77 State Registration No. _____
 or Agency _____

Certified Cor. Record Prepared? Yes No _____ Filed At: _____ Date _____ 11

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

12

13