

USDA-FOREST SERVICE

Index
File No. E-19

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or
Survey No. _____ No. _____

T 6S. R. 30E. R.D. Ukiah County Umatilla

Merid. Willamette N.F. Umatilla State Oregon

CORNER DIAGRAM



T. 6S., R. 30E.

1/4 S.2
S.11

DESCRIBE CORNER MONUMENT FOUND

None

Set brass cap

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From intersection of U.S. Forest Roads 419N and 537N, go East by South 3.2 miles to intersect in road. From intersection, go South 0.2 miles and corner is 200 ft. North of road.

Signature

David H. K. [unclear]

Title

Division

OPLS

Headquarters

933

Date

7-77

7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 2½" x 30" iron pipe with brass cap.
 Pipe is 20" in ground.
 Mound of stones to cap.

Stamped:

T. 6S., R. 30E.

¼	S.2
	S.11

1977
 PLS 933

9

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

A 18" pine bears N. 70°00' E. 61.3 ft.

A 14" pine bears S. 31°58' E. 38.0 ft.

Set steel fence post 2 ft. ~~North~~ corner w/sign.

Painted red band around BT trees w/sign.

10

Work Done By T. Hamby Title Party Chief Date 6/23/77 State Registration No. or AgencyCertified Cor. Record Prepared? Yes No Filed At: Date

11

REMARKS

Index File No.

T.

R.

M.

Tract or Surv. No.

Cor.

12

13