


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

E-a

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

Set 32" X 2" flanged iron pipe with brass cap marked:
From Which

Douglas Fir, 10" Dia., BRS. N14⁰E., 12.4 Ft. Dist.
Marked: W 1/16 S6 BT

Douglas Fir, 14" Dia., BRS. S28¹⁰W., 54.2 Ft. Dist.
Marked: W 1/16 S7 BT

6' iron fence post with "Survey Monument" sign within 5' of corner.

All B.T. have BT tag and painted red stripe. New BTs have brass washer stamped:
PLS 346; nailed to lower blaze.

T6S R30E
W 1/16 S6
S7
1979
PLS 346

Office of County Surveyor County of Umatilla
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the day of
..... by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

RECEIVED BY
Umatilla County Surveyor
Date 10-17-79
Rec'd By mjs
No. Q-1171-B

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Wayne O. Harris
OREGON
MAY 6, 1955
WAYNE O. HARRIS
346

E-e