

Index
File No.

CORNER RECORD (SEARCH)

(Ref. FSM 5151.4)

Tract or
Survey No.

Tower Unit

Cor.
No. AP-388T. 6 S. R. 35 E.
Merid. WillametteR.D. North Fork John Day
N.F. UmatillaCounty Umatilla
State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found a 3 1/4" aluminum cap, set flush with the ground.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

12" Western Larch Snag, S. 67 W., 17.0 feet, with burnt out double blaze.
17" Western Larch Snag, N. 8 W., 37.6 feet, with burnt out double blaze.

PHOTO IDENTIFICATION DATA

Photo No.
Filed At.
Object Ident.
Ident. By

Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the jct. Of roads 52 and 5226 travel northerly on 5226 approx. 3.94 miles. The corner is located approx. 200 feet westerly of the road.

PLANE COORDINATE POSITION DATA

State: Zone:

X:

Y:

Datum:

Signature

D. Schlaich

Title

Land Surveyor

Division

Headquarters

S.O.

Date

10/28/1997

FS-7100-52 (3/97)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

RM, 5/8" X 36" rebar, with yellow plastic cap stamped "UMATILLA N.F.", set 32" in the ground, N. 68 3/4 E., 16.4 feet.
RM, 5/8" X 36" rebar, with red plastic cap stamped "UMATILLA N.F." set 27" in the ground, S. 7 1/2 W., 15.55 feet.

Work Done By D. Schlaich

Title

Land Surveyor

Date 10/28/1997

State Registration No.
or Agency

Certified Corner Record Prepared ?

Yes

No

Filed At:

Date

REMARKS

USDA-FOREST SERVICE

Index

File No.

T. 6 S. R. 35 E.

Merid. WILLAMETTE

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

R.D. NFJD

N.F. UMATILLA

County UMATILLA

State OREGON


Tract or

Survey No. Tower Unit

Cor.

No. AP-388

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

NONE

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

NONE

PHOTO IDENTIFICATION DATA

Photo No.:

Filed At.:

Object Ident.:

Ident. By:

Signature

DESCRIBE CORNER RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the jct. of FS rds. 52 and 5226 travel northerly on 5226 approx. 3.94 miles. The corner is located approx. 200 westerly of the road.

PLANE COORDINATE POSITION DATA

State: Oregon Zone: North

X: 2,504,638.22'

Y: 499,377.20'

Datum: NAD1927

Signature

D. Schlaich

Title

Land Surveyor

Division

Headquarters

S.O.

Date

06-1993

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

5/8" by 36" rebar, with a 3 1/4" aluminum cap, 35" in the ground, marked "NFJD WILDERNESS TOWER UNIT AP-388 RLS2308 1993".

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

11" Western Larch, S. 66° W., 17.0 ft., mkd. "WB/388"BT" on double blaze.

17" Western Larch, N. 7° W., 37.6 ft., mkd. "WB/388"BT" on double blaze.

Work Done By **D. Schlaich**

Title Land Surveyor

Date 06-1993

State Registration No.
or Agency

Certified Cor. Record Prepared ? **NO**

Filed At:

Date

REMARKS

Index File No.

T.

6 S.

R.

35 E.

M.

W.M.

Tract or Survey No.

Cor.

AP-388