

USDA-FOREST SERVICE

Index

File No. C-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. E 1/4


T 75. R. 34 E

R.D. NORTH FORK JOHN DAY County Grant

Merid. WILLAMETTE

N.F. DMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

STONE, 13"X11"X5", w/CHISEL MARKS, AT RECORD BEARING AND DISTANCE FROM REMAINING B.T.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND 2

(12") LODGEPOLE PINE, S. 33°W, 46 LINKS, w/SCRIBES 45 IN UPPER BLAZE. LOWER BLAZE HEALED. TREE IS SNAG.

PHOTO IDENTIFICATION DATA 6

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA 7

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER 3

TAKE ROAD 510 OFF 52 TO POINT 0.6 MILE PAST LINE TAG TO COR. $\frac{35}{21}$ SEE CORNER CE $\frac{1}{16}$ SOUTH ACROSS CREEK IN FIELD. GO TO $\frac{1}{16}$ COR., GO $\frac{1}{4}$ MILE EAST ALONG POSTED LINE TO $\frac{1}{4}$ COR.

Signature

Clayton J. Matilla

Title

LAND SURVEYOR

Division

Headquarters

Date

10/24/86

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

A 2 1/2" DIAM. ALUM. CAP ON A 2 1/2" x 30" Alum Pipe at Corner
 and buried cornerstone alongside pipe. Raised stone mound
 around pipe. Set steel posts 4' ± W. & N. with Mon., Athn. &
 property Bndry. signs attached.

T75 R34E
 4
 S2 | S1
 RPLS 1910
 1985

9

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

① 9" D.B.H. Lodgepole Pine, S. 72 1/2° W., 8.1', scribed 1/4 S2BT.
 ② 13" D.B.H. Lodgepole Pine, S. 42° E., 19.2', scribed 1/4 S1BT.
 Set a brass washer mkd. RPLS 1910 Btwn. B&T of each B.T.,
 set B.T. Tags, Athn. signs, painted bands and faces red.

10

Work Done By C.J. MARTIN Title LAND SURVEYOR Date 10/24/86 State Registration No. L.S. 1910
 or Agency

Certified Cor. Record Prepared? Yes No Filed At: Grant Co. Courthouse Date 12/85

11

REMARKS

Index File No.
 C-21

T. 7 S, R. 34 E. M. WILLAMETTE Tract or Surv. No.

Cor. 1/4
 S.2 | S.1

12

13

Index

File No. C-21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 7S R. 34E

R.D. Dale

County Grant


Merid. Will

N.F. Umatilla

State Oregon

CORNER DIAGRAM

T7S R34E



DESCRIBE CORNER MONUMENT FOUND

Stone of record size found in correct position but no scribes visible.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Orig 12" pine is now dead but still standing. Upper blaze is open and scribing "45" is visible. Lower blaze is healed. Bears $S33^{\circ}W$, 30.36 ft from corner.
 Orig 8" pine is down and rotten. A piece of wood appears to have some scribe marks on it. Bears $S80^{\circ}E$, 53.46 ft from corner.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Location is approx. 300 yds East of road
 5300 510

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Cathy M. Mc Guire

Title

Volunteer

Division

Headquarters

50

Date

8/29/84

7100-52-(3,68)

CORNER RECORD (PERPETUATION)

MONUMENT : DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____
Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor.