

Field Notes of Road No.767

Commencing at a point N,16°E 333 feet distance from the S,W,Corner of Section 7.T.2.N.R.32.E.W.M.Set Post 30 feet North of initial point Marked R.767 Dug pits E,&W, and raised Mound 4 feet Base 18 ins,high around post.

Thence S,36°W	3,00	Distant.....	A,1
.. S,44°W,	2,00	5,00 .....	A,2
.. S,35°W,	1,00	6,00 .....	A,3
.. S,15°W,	.50	6,50	Cross O.W.R.R.
	5.10	6,90	Umatilla River 320 feet across
	11,00	17,00	To A.point.20 feet West of the R,R,Right of Way thence following paralel with and 80 ft, from said right of way,
Curve to right	5,00	22,00 .....	A,4
Thence S,41° W,	14,00	36,00 .....	A,5
Curve to left	13,50	49,50 .....	A,6
Thence N,64°E	2,15	51,65	Cross R,R,.....
.. S,32°E	2,91	54,56	paralel with and 20 ft,from R,R,.....
.. S,39°E	20,65	75,21.....	A,9
.. S,57°E	4,79	80,00	1,M,Set post 20ft, to left Marked 1,M,dug pits N,W,&,S,E, and raised mound 4 ft,Base 18 ins, high around post,
.. S,57°E	11,40	11,40 .....	A,10
.. S,39°E	5,45	16,95 .....	A,11
.. S,24°E	9,77	26,72 .....	A,12
.. S, 9°E	4,60	31,32	to point 20ft,East of R,R,Right of way A,13
.. S, 21°E	6,00	37,32	paralel with R,R, A,14
.. S,31°E	2,23	39,55 .....	A,15
.. S,35°E	15,90	55,45, .....	A,16
.. S,38°W	2,91	57,36	Cross to west side of R,R, A,17
.. S,21°E	2,25	59,61	irrigation ditch 2 ft,wide
	8,00	65,36	paralel with and .20 ft,from R,R, A,18
.. S,17°E	5,95	71,31 .....	A,19
.. S,30°W	1,40	72,71	Cross Birch Creek A,20
.. S,35°E	2,75	75,46 .....	A,21
.. S,11°E	4,54	80,00	2,M,A,Willow 20ft, to left Marked 2,M,A,22
.. S,23°E	5,00	5,00 .....	A,23
.. S,12°E	2,05	7,05 .....	A,24
.. S,50°E	1,65	8,70	point 20 ft,west of R,R,Right of way A,25
.. S,20°E	5,00	13,70	paralel with R,R,& 20 ft,west A,26
Curve left	25,00	38,70	paralel with and 20 from R,R, A,27
Thence S,62°E	7,00	45,70 .....	A,28
.. S,58°E	5,75	51,45, .....	A,29
.. S,67°E	2,95	54,40.....	A,30
.. S,62°E	11,00	65,40.....	A,31
Curve left	14.60	80,00	3,M, set post Marked 3,M, dug pits S,E,&,N,W and raised mound 4 ft,Base 18 ins high,
	3,40	3,40.....	A,32
Thence S,51°E	21,00	24,40.....	A,33
Curve left	10,00	34,40.....	A,34
Thence S,68°E	9,00	43,40.....	A,35
Curve Right	12,00	55,40.....	A,36
Thence S,37°E	8,00	63,40	R,T,Set post 20 ft, to Right Marked R,T,No,767
			Dug pits S,E,&,N,W, and raised Mound 4 ft,Base 18 ins high around Post.

I hereby certify that the foregoing Field Notes of Road No.767 are Correct as Surveyed by me on the 10th, and the 15th, days of September

1914. *John W. Tomlin* Deputy County Surveyor.

*Plus \$2.00*  
*\$5.00*  
*\$1.00*  
*70 ft from R.R.*  
*Line \$200*  
*Full \$584*  
*\$200*  
*Paper 16.00*  
*Budget 600*  
*Pubs 250*  
*Grading \$100*  
*Grading \$200*