

OREGON CORNER RESTORATION FORM

T1N R31E Z25

Section 36, Township 1N, Range 31E,
County Umatilla, Date November 15, 2004.

- Condition Report
- Not Found
- Remonumented
- Unrecorded
- Surveyed in
- Referenced out

Township corner common to Township 1 North, Ranges 31 and 32 East, W.M., Umatilla County, Oregon.

Previous Renewals / Surveys, etc.


The corner was originally set by David P. Thompson under Contract No. 79 dated July 26, 1858. His record Reads: Set post for corner to Township 1 North, Ranges 31 and 32 East and build mound of earth as per instructions. Surveyor David Haddock, under County Survey 97-140-C accepted the testimony of long time adjoining land owner, Mr. Bob Sacrison, along with the evidence of the corner. His record reads: I set a 1.25" x 30" galvanized iron pipe, with 2.25" brass cap flush with the ground between the posts of an H brace and on the east side of a gate.

Monument and accessories found: (Condition and source)

I found the brass cap set by Dave Haddock in good condition and firmly set.

DIAGRAM

SKETCH



Monument and accessories set: (Procedures and description)
None.

Location and Comments
SPC Oregon North, NAD 83-91
Northing = 678,190.23 ift
Easting = 8,619,520.82 ift

Compass Declination

Surveyor's Seal

Witnessed By:
RECEIVED BY:
Umatilla County Surveyor
Date: 5-05
Rec'd By: KK
No. 05-111-C

Firm / Agency
Witness Tree Surveying
P.O. Box G
Pilot Rock, OR 97868
Party Chief
Stephen K. Haddock, PLS

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Stephen K. Haddock
OREGON
JULY 9, 2001
STEPHEN K. HADDOCK
58295LS

RENEWAL DATE 6-30-05