

OREGON CORNER RESTORATION FORM

Section 4 Township 1N Range 32E
County Umatilla Date: August 17, 2009


Corner Designation: 1N32C13 Condition Report Only
Not found
Remonumented
Unrecorded
Surveyed in
Referenced out

Previous Renewals / Surveys, etc.
Corner originally set by Daniel Chaplin under contract No. 107, Dated September 21, 1864.
His record reads: Set stone, 14 x 12 x 6, for 1/4 sec. cor. David L. Haddock under survey 05-150-B states: found record stone, set brass cap.

Monument and Accessories found: (condition and source)
I found the brass cap from survey 05-150-B in good condition as reported.

DIAGRAM

SKETCH



MONUMENT (S) AND ACCESSORIES SET (Procedures and Description)
None. This certificate is being filed to report the state plane coordinates.

This monument was tied using a Trimble R7/R8 RTK GPS system.

Location and comments
NAD 83/1991 State Plane Coordinate
Oregon North Zone
N = 707,484.67 ift
E = 8,635,322.55 ift

Compass Declination

Surveyors Seal

RECEIVED BY:
Umatilla County Surveyor
Date: 6-10
Rec'd By: SK
No. 10-93-C

Firm / Agency
Witness Tree Surveying
Address
P.O. Box G
Pilot Rock, OR 97868
Party Chief
Stephen K, Haddock

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Stephen K. Haddock

OREGON
JULY 9, 2001
STEPHEN K. HADDOCK
56295LS

RENEWAL DATE 6-30-11