

Record of Corner Monumentation

K-16

History of original corner establishment:

NE 1/16 corner, Section 15, was monumented by C.E. Redfield during his 1919 circa. He set a 2 1/2" brass cap on a 36 inch pipe in a plowed field.

Description of corner evidence found:

I found no trace of this monument as it is located in a field that has been farmed for many years. No doubt the monument has been destroyed during farming operations.

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 5/8" x 36" iron pin with a 2 1/2" Brass Cap, being stamped as shown in the diagram. I drove the pin flush to the ground, then placed a mound of large stone about the monument.

Diagram:

NE 1/16
S 15
T 1 N R 33 E
2002
ORLS 645

REGISTERED
PROFESSIONAL
LAND SURVEYOR

James H. Hambleton

02-20-03

OREGON
JULY 10, 1964
JAMES H. HAMBLETON
645

03-35-B