

Index File No. J-20 #

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or Survey No. _____

Cor. No. _____


T IN R. 35E

R.D. WALLA WALLA County UMATILLA

Merid. WILL

N.F. UMATILLA State OREGON

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

BRASS CAPPED IRON PIPE MARKED AS SHOWN IN THE CORNER DIAGRAM IS OUT OF THE GROUND & WIRED TO FENCE CORNER POST, FENCE PROJECTING EAST & N20°E.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

ORIG. 20", NOW 30" PONDEROSA PINE IS LIVE, UPPER BLAZE NEARLY SHUT. LOWER BLAZE BURNT OUT, TREE HAS 3

NO TRESPASSING SIGNS NAILED ABOVE BLAZE, BRZ S56 3/4 W 186 LKS.

ORIG. 20", NOW 30" PONDEROSA PINE W/ SCRIBES VISIBLE ON PREVIOUSLY OPENED BLAZE (UPPER), LOWER BLAZE HEALED SHUT, BEARS N55°W, 188 LINKS.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

HAS BLM BT SIGN ATTACHED, I PLACE LSM SIGNS ON BOTH BTs,

CORNER IS 15+ FEET NORTH OF ROAD 010.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature

Title

Division

Headquarters

Date

FS-7100-52 (3/68)

Dennis L. Hayward PLS 1636

S.O.

8-30-89

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

9

ACCESSORIES : DESCRIBE NEW BT's WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared ? Yes No Filed At: _____ Date _____

REMARKS

12

Index File No. T. R. M. Tract or Surv. No. Cor. 13