

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 1 N R. 35 E Mer.

1/4 Corner common to Sections
S. 12, and S. 13

DESCRIPTION OF CORNER

Corner consists of a mound of rocks

Dimension above ground 2.0 inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

NW SW SE NE

Mound of _____ is located _____

m Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? could not find several

rocks

JCM
Signature.

T. _____ R. _____ Mer. _____

8-3027

(Make sketch of topography near Corner.)

| | | | |
|--|------|--|------|
| | | | |
| | Sec. | | Sec. |
| | | | |
| | | | |
| | Sec. | | Sec. |
| | | | |

Metal Location Poster is on a _____
tree _____ inches diameter, on the _____
side of _____
from which this Corner bears _____
_____ chains distant.

Give any further facts which will aid in finding this
Corner again.

P



USDA-FOREST SERVICE


Index File No. J-23

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____ Cor. No. J-23

T 1 N R. 35 E R.D. _____ County _____
Merid. Williamette N.F. _____ State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

No monument found

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

1/4 corner may be driven to by turning North off the Light Ridge road on a trail which turns off just west of a small stock watering reservoir at the edge of the timber.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency

Signature Hillis, Christy Title Ranga Cons - F. Aid Division _____ Headquarters BuRang, Ora. Date 8-24-71 7100-52-(3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set corner 1/2 way between Sac, Corners,
the corner is a steel post with a location tag attached,
set a large mound of straw at the base of the post,

ACCESSORIES : DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

9

10

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

11

REMARKS

1/4 corner is adjacent to a large rock duck in the
Forest Service fence (west side of ayata)

12