

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

Index File No. T-1/2

T 1N. R. 37E.

R.D. Walla Walla County Umatilla

Merid. W.M.

N.F. Umatilla State OR

CORNER DIAGRAM

DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

None

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

FALLS SOUTH OF CREEK IN BOTTOM LAND.

PHOTO IDENTIFICATION DATA

Photo No. _____

Filed At. _____

Object Ident. _____

Ident. By _____

Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency _____

Signature

Michael P. Zefema P.L.S.

Title

Division

Headquarters

Date

10/93

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

At a section subdivision as determined by this survey set a 3/4" aluminum cap on a 2 1/2" x 30" aluminum pipe, 26" in the ground.

TINR37E
C 116-80
S 30
PLS 2535
1993

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

8" White fir Bears S. 16 1/2° E., 46.4 Feet scribed C 11680S30BT.

1 1/2" aluminum cap (PLS 2535) on a 5/8" x 24" rebar, bears N. 74 1/4° E., 10.5 Ft.

Work Done By LeJeune Title PLS. Date 9/93 State Registration No. or Agency 2535 10

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____ 11

REMARKS

Index File No.

T-1/2

T.
IN.

R.
37E.

M.
W.M.

Tract or Surv. No.

Cor.

12

13